



IMPORTANT!!!!

RSSS TROUBLESHOOTING BULLETIN

November 18, 2002

*****BROTHER LASER PRINTER FORM FEED*****

PROBLEM: "MY BROTHER LASER PRINTER WILL NOT EJECT SCREEN SHOTS OR THE LAST PAGE OF SOME OF MY REPORTS. IS THERE SOME OTHER WAY TO TELL THE PRINTER TO EJECT THE PAGE WITHOUT HAVING TO PUSH THE GO BUTTON?"

SOLUTION: THE AUTO FF TIME CAN BE SET TO EJECT THE PRINT JOB HELD BY THE PRINTER. THIS FEATURE IS TURNED ON BY DESIGNATING THE NUMBER OF SECONDS FOR THE AUTO FORM FEED COMMAND. THIS IS DONE FROM THE MENU SYSTEM LOCATED JUST BELOW THE LED WINDOW.

FOLLOW THESE STEPS:

1. PRESS THE + BUTTON 5 TIMES FOR "PRINT MENU"
2. PRESS SET TO ENTER
3. PRESS THE + BUTTON 5 TIMES FOR "AUTO FF TIME"
4. PRESS SET TO ENTER
5. PRESS THE + BUTTON UNTIL YOU REACH 15
6. PRESS SET TO SAVE THIS SETTING
7. NOW PRESS THE "GO" BUTTON, YOU'RE DONE!

NOTE: IF YOU MISS A STEP OR PRESS THE WRONG BUTTON JUST PRESS THE GO BUTTON AND START OVER.